



BPL:

Part of the former national blood authority.

The Problem

BPL suffered from serious scaling on ball valves in their urinal systems caused by hard water. This results either in urinals flushing continuously or not at all.

The Solution

BPL decided to install a catalytic SCALETRON unit manufactured by Fluid Dynamics on an initial bank of thirty toilets to prevent the scale build up.

The results were excellent and within a period of three months the scale problems were literally "flushed away"
