

# LG Sonic Applications - BEFORE & AFTER pics

## CANAL

**BEFORE:** Blue green algae caused foul odor and toxic water



**AFTER:** Foul odor disappeared; dramatic reduction in toxicity levels; clearer water



## WATERFALL

**BEFORE:** Foul smelling & toxic water pumped from the canal above



**AFTER:** Odour-free cleaner water resulting from LG Sonic treatment in the canal above



# LG Sonic Applications - BEFORE & AFTER pics

## BOAT LAKE

**Before:** This is how the water looked in March when ambient temperature average was 27 C°



**After:** Increased clarity in June despite increase in ambient temperature average to 37 C°




# LG Sonic Applications - BEFORE & AFTER pics

## LAKE B

**BEFORE:** Blue green algae caused foul odor and murky toxic water



**AFTER:** Foul odor disappeared; dramatic reduction in toxicity levels; cleaner, clearer water



Samples collected from both lakes (A & B) after 3 weeks of installing LG Sonic XXL plus in Lake B